



# M15HP Parts Identification



Electrical isolation is the responsibility of the OEM.  
 Isolation must be maintained on the power supply lines, the digital lines and the analog lines.



17517 Fabrica Way, Suite H; Cerritos, CA 90703 USA  
 P 714.367.2848 - F 714.367.2852  
 www.mediaidinc.com - info@mediaidinc.com

Specifications subject to change without notice.